

STRUCTURES INSPECTION FIELD REPORT

SPECIAL MEMBER INSPECTION

2-DIST
01

B.I.N.
5CV

BR. DEPT. NO.
A-13-029

CITY/TOWN ASHFIELD	8-STRUCTURE NO. A13029-5CV-MUN-BRI	11-Kilo. POINT 000.000	90-ROUTINE INSP. DATE Jul 18, 2023	93*-SPEC. MEMB. INSP. DATE Jul 23, 2024
07-FACILITY CARRIED HWY SMITH BR RD	MEMORIAL NAME/LOCAL NAME		27-YR BUILT 1939	106-YR REBUILT 1964
06-FEATURES INTERSECTED WATER SMITH BROOK	26-FUNCTIONAL CLASS Rural Local	DIST. BRIDGE INSPECTION ENGINEER <i>M. P.E. McCabe</i>		
43-STRUCTURE TYPE 302 : Steel Stringer/Girder	22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER R. Mancari <i>Reed Mancari</i>	
107-DECK TYPE 1 : Concrete Cast-in-Place	WEATHER Sunny	TEMP. (air) 18°C	TEAM MEMBERS M. RANZONI <i>Matthew Ranzoni</i>	

WEIGHT POSTING *Not Applicable* **X**

Actual Posting	H	3	3S2	Single
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Recommended Posting	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Waived Date: 00/00/0000 EJDMT Date: 00/00/0000

Signs In Place (Y=Yes, N=No, NR=Not Required)

At bridge		Advance	
N	S	N	S
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Legibility/Visibility

PLANS (Y/N): **Y**

(V.C.R.) (Y/N): **N**

TAPE#: _____

RATING

Rating Report (Y/N): **N** Date: ----

Recommend for Rating or Rerating (Y/N): **N** If YES please give priority: HIGH () MEDIUM () LOW ()

REASON: **Rating requested after 7/18/23 inspection.**

Inspection data at time of existing rating
I 58: - I 59: - I 60: - I 62: - Date : 00/00/0000

SPECIAL MEMBER(S):

	MEMBER	CRACK (Y/N):	WELD'S CONDITION (0-9)	LOCATION OF CORROSION, SECTION LOSS (%), CRACKS, COLLISION DAMAGE, STRESS CONCENTRATION, ETC.	CONDITION		INV. RATING OF MEMBER FROM RATING ANALYSIS			Deficiencies
					PREVIOUS	PRESENT	H-20	3	3S2	
					(0-9)	(0-9)				
A	Item 59.4 - Girders or Beams	N		See remarks in comments section.	4	3	Not Rated			S-A
B										
C										
D										
E										

List of field tests performed:

	I-58	I-59	I-60	I-62
(Overall Previous Condition)	6	4	7	-
(Overall Current Condition)	6	3	7	-

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency - Deficiencies which are minor in nature, generally do not impact the structural integrity of the bridge and could easily be repaired. Examples include but are not limited to: Spalled concrete, Minor pot holes, Minor corrosion of steel, Minor scouring, Clogged drainage, etc.

S= Severe/Major Deficiency - Deficiencies which are more extensive in nature and need more planning and effort to repair. Examples include but are not limited to: Moderate to major deterioration in concrete, Exposed and corroded rebars, Considerable settlement, Considerable scouring or undermining, Moderate to extensive corrosion to structural steel with measurable loss of section, etc.

C-S= Critical Structural Deficiency - A deficiency in a structural element of a bridge that poses an extreme unsafe condition due to the failure or imminent failure of the element which will affect the structural integrity of the bridge.

C-H= Critical Hazard Deficiency - A deficiency in a component or element of a bridge that poses an extreme hazard or unsafe condition to the public, but does not impair the structural integrity of the bridge. Examples include but are not limited to: Loose concrete hanging down over traffic or pedestrians, A hole in a sidewalk that may cause injuries to pedestrians, Missing section of bridge railing, etc.

URGENCY OF REPAIR:

I = Immediate- [Inspector(s) immediately contact District Bridge Inspection Engineer (DBIE) to report the Deficiency and to receive further instruction from him/her].

A = ASAP- [Action/Repair should be initiated by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) upon receipt of the Inspection Report].

P = Prioritize- [Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available].

X=UNKNOWN N=NOT APPLICABLE H=HIDDEN/INACCESSIBLE R=REMOVED

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8.-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
-----------------------	---------------	---------------------------	--	---------------------------------

REMARKS

BRIDGE ORIENTATION

Smith Branch Road travels north and south. Smith Brook flows west to east. This single span structure consists of five steel beams supporting a reinforced concrete deck with a gravel wearing surface. The beams and bays are numbered west to east, upstream to downstream, in accordance with the 2015 Bridge Inspection Handbook. See sketch 1 and photos 1 & 2.

ITEM 59 - SUPERSTRUCTURE

Item 59.4 - Girders or Beams

All beams have widespread rusting with random bird nests on the bottom flanges. See photo 2.

Beams 1, 2, 4 and 5, at the north ends, have moderate to severe rusting, with up to 100% section loss. See sketches 2 - 5 and photos 3 - 6.


Beams 2 and 5, at the north ends, have minor out of plane bending. See photos 4 & 6.

Sketch / Photo Log

Sketch 1 : Framing plan.
 Sketch 2 : Beam 1 section loss.
 Sketch 3 : Beam 2 section loss.
 Sketch 4 : Beam 4 section loss.
 Sketch 5 : Beam 5 section loss.
 Photo 1 : General topside, looking south.
 Photo 2 : General underside, looking south.
 Photo 3 : Beam 1 north end section loss.
 Photo 4 : Beam 2 north end section loss.
 Photo 5 : Beam 4 north end section loss.
 Photo 6 : Beam 5 north end section loss.

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
------------------------------	----------------------	----------------------------------	--	--

SKETCHES



SOUTH ABUTMENT

NORTH ABUTMENT


Sketch 1: Framing plan.

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
------------------------------	----------------------	----------------------------------	--	--

SKETCHES

Beam 1 – North End (West Elevation)


Original Section: 16" WF 50#
Original Flange = 0.625"
Original Web = 0.375"



Sketch 2: Beam 1 section loss.

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
------------------------------	----------------------	----------------------------------	--	--

SKETCHES




Sketch 3: Beam 2 section loss.

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
------------------------------	----------------------	----------------------------------	--	--

SKETCHES


Beam 4 – North End (East Elevation)



Sketch 4: Beam 4 section loss.

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
------------------------------	----------------------	----------------------------------	--	--

SKETCHES



Original Section: 16" WF 50#
 Original Flange = 0.625"
 Original Web = 0.375"

Beam 5 - East Elevation

Sketch 5: Beam 5 section loss.

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8.-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS



Photo 1: General topside, looking south.



Photo 2: General underside, looking south.

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8.-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS



Photo 3: Beam 1 north end section loss.



Photo 4: Beam 2 north end section loss.

CITY/TOWN ASHFIELD	B.I.N. 5CV	BR. DEPT. NO. A-13-029	8.-STRUCTURE NO. A13029-5CV-MUN-BRI	INSPECTION DATE JUL 23, 2024
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS

Photo 5: Beam 4 north end section loss.



Photo 6: Beam 5 north end section loss.