

STRUCTURES INSPECTION FIELD REPORT

2-DIST  
01

B.I.N.  
0EF

OTHER INSPECTION

BR. DEPT. NO.  
A-13-024

CITY/TOWN <b>ASHFIELD</b>	8.-STRUCTURE NO. <b>A13024-0EF-MUN-NBI</b>	11-Kilo. POINT <b>000.000</b>	90-ROUTINE INSP. DATE <b>Mar 21, 2025</b>	INSPECTION DATE <b>Jul 8, 2025</b>
07-FACILITY CARRIED <b>HWY WILLIAMSBURG</b>	MEMORIAL NAME/LOCAL NAME	27-YR BUILT <b>1938</b>	106-YR REBUILT <b>0000</b>	*YR REHAB'D (NON 106) <b>0000</b>
06-FEATURES INTERSECTED <b>WATER CREAMERY BROOK</b>	26-FUNCTIONAL CLASS <b>Major Collector</b>	DIST. BRIDGE INSPECTION ENGINEER <i>M. P.E. McCabe</i>		
43-STRUCTURE TYPE <b>302 : Steel Stringer/Girder</b>	22-OWNER <b>Town Agency</b>	21-MAINTAINER <b>Town Agency</b>	TEAM LEADER R. Mancari <i>Reed Mancari</i>	
107-DECK TYPE <b>1 : Concrete Cast-in-Place</b>	WEATHER <b>Cloudy</b>	TEMP. (air) <b>25°C</b>	TEAM MEMBERS <b>E. GEMINDER</b> <i>E. Geminder</i>	

WEIGHT POSTING	<i>Not Applicable</i>				Signs In Place (Y=Yes,N=No, NR=Not Required) Legibility/ Visibility	At bridge		Advance		PLANS (Y/N): <input checked="" type="checkbox"/>
	H	3	3S2	Single		E	W	E	W	(V.C.R.) (Y/N): <input type="checkbox"/>
	Actual Posting	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>				
Recommended Posting	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Waived Date:	<input type="text" value="00/00/0000"/>	EJDMT Date:	<input type="text" value="00/00/0000"/>							

RATING	Rating Report (Y/N): <input checked="" type="checkbox"/>	Date: <input type="text" value="08/01/2004"/>	Recommend for Rating or Rerating (Y/N): <input type="checkbox"/>	If YES please give priority: HIGH ( ) MEDIUM ( ) LOW ( )
Inspection data at time of existing rating I 58: 7 I 59: 7 I 60: - I 62: - Date :00/00/0000			REASON: <input type="text"/>	

MEMBER(S):	MEMBER	CRACK (Y/N):	WELD'S CONDITION (0-9)	LOCATION OF CORROSION, SECTION LOSS (%), CRACKS, COLLISION DAMAGE, STRESS CONCENTRATION, ETC.	CONDITION		INV. RATING OF MEMBER FROM RATING ANALYSIS			Deficiencies
					PREVIOUS	PRESENT	H-20	3	3S2	
					(0-9)	(0-9)				
A	Item 60.1.a - Pedestals	N	N	See remarks in comments section.	4	2	Not Rated			S-A
B										
C										
D										
E										

List of field tests performed:	I-58	I-59	I-60	I-61	I-62	
	(Overall Previous Condition)	<input type="text" value="6"/>	<input type="text" value="4"/>	<input type="text" value="6"/>	<input type="text" value="6"/>	<input type="text" value="-"/>
	(Overall Current Condition)	<input type="text" value="6"/>	<input type="text" value="4"/>	<input type="text" value="6"/>	<input type="text" value="6"/>	<input type="text" value="-"/>

**DEFICIENCY:** A defect in a structure that requires corrective action.

**CATEGORIES OF DEFICIENCIES:**

**M= Minor Deficiency** - Deficiencies which are minor in nature, generally do not impact the structural integrity of the bridge and could easily be repaired. Examples include but are not limited to: Spalled concrete, Minor pot holes, Minor corrosion of steel, Minor scouring, Clogged drainage, etc.

**S= Severe/Major Deficiency** - Deficiencies which are more extensive in nature and need more planning and effort to repair. Examples include but are not limited to: Moderate to major deterioration in concrete, Exposed and corroded rebars, Considerable settlement, Considerable scouring or undermining, Moderate to extensive corrosion to structural steel with measurable loss of section, etc.

**C-S= Critical Structural Deficiency** - A deficiency in a structural element of a bridge that poses an extreme unsafe condition due to the failure or imminent failure of the element which will affect the structural integrity of the bridge.

**C-H= Critical Hazard Deficiency** - A deficiency in a component or element of a bridge that poses an extreme hazard or unsafe condition to the public, but does not impair the structural integrity of the bridge. Examples include but are not limited to: Loose concrete hanging down over traffic or pedestrians, A hole in a sidewalk that may cause injuries to pedestrians, Missing section of bridge railing, etc.

**URGENCY OF REPAIR:**

**I = Immediate-** [Inspector(s) immediately contact District Bridge Inspection Engineer (DBIE) to report the Deficiency and to receive further instruction from him/her].

**A = ASAP-** [Action/Repair should be initiated by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) upon receipt of the Inspection Report].

**P = Prioritize-** [Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available].

X=UNKNOWN      N=NOT APPLICABLE      H=HIDDEN/INACCESSIBLE      R=REMOVED

CITY/TOWN <b>ASHFIELD</b>	B.I.N. <b>0EF</b>	BR. DEPT. NO. <b>A-13-024</b>	8.-STRUCTURE NO. <b>A13024-0EF-MUN-NBI</b>	INSPECTION DATE <b>JUL 8, 2025</b>
------------------------------	----------------------	----------------------------------	---	---------------------------------------

## REMARKS

### **BRIDGE ORIENTATION**

Williamsburg Road travels north and south. Creamery Brook flows from west to east. This single span structure consists of six steel beams, supporting a concrete deck, with an asphalt wearing surface. The beams and bays are numbered from west to east, upstream to downstream, in accordance with the 2004 Rating Report. **See Sketch 1 & Photos 1 & 2.**

### **GENERAL REMARKS**

This inspection was performed to document the placement of roadway barriers, and to assess the condition of the bearing pedestals.

### **ITEM 59 - SUPERSTRUCTURE**

#### **Item 59.9 - Bearing Devices**

Along the south abutment, the bearings are severely undermined, with deteriorated pedestals. Refer to Item 60.1.a - Pedestals.

### **ITEM 60 - SUBSTRUCTURE**

#### **Item 60.1 - Abutments**

##### **Item 60.1.a - Pedestals**

At the south abutment, the pedestals are cracked and spalled, with up to 90% loss of bearing area (beam 2 bearing). **See Sketch 3 and Photos 3 – 7.**


At the north abutment, the pedestals have minor to moderate cracking, and isolated minor spalls.

### **Sketch / Photo Log**

- Sketch 1 : Framing plan.
- Sketch 2 : Horizontal clearance.
- Sketch 3 : Bearings 1 – 5, south abutment. From Routine & Special Member Report, dated 3/21/25.
- Photo 1 : General topside, looking north.
- Photo 2 : General underside, looking south.
- Photo 3 : South bridge seat, with deteriorated pedestals and bearings.
- Photo 4 : South abutment, beam 1 bearing.
- Photo 5 : South abutment, beam 2 bearing.
- Photo 6 : South abutment, beam 4 bearing.
- Photo 7 : South abutment, beam 6 bearing.

CITY/TOWN <b>ASHFIELD</b>	B.I.N. <b>0EF</b>	BR. DEPT. NO. <b>A-13-024</b>	8-STRUCTURE NO. <b>A13024-0EF-MUN-NBI</b>	INSPECTION DATE <b>JUL 8, 2025</b>
------------------------------	----------------------	----------------------------------	--	---------------------------------------


**SKETCHES**



Sketch 1: Framing plan.

CITY/TOWN <b>ASHFIELD</b>	B.I.N. <b>0EF</b>	BR. DEPT. NO. <b>A-13-024</b>	8.-STRUCTURE NO. <b>A13024-0EF-MUN-NBI</b>	INSPECTION DATE <b>JUL 8, 2025</b>
------------------------------	----------------------	----------------------------------	---	---------------------------------------


**SKETCHES**




**Sketch 2: Horizontal clearance.**

CITY/TOWN <b>ASHFIELD</b>	B.I.N. <b>0EF</b>	BR. DEPT. NO. <b>A-13-024</b>	8.-STRUCTURE NO. <b>A13024-0EF-MUN-NBI</b>	INSPECTION DATE <b>JUL 8, 2025</b>
------------------------------	----------------------	----------------------------------	---	---------------------------------------


**SKETCHES**



PLAN  
BEARING 1  
SOUTH ABUTMENT (FIXED)



PLAN  
BEARING 2  
SOUTH ABUTMENT (FIXED)




PLAN  
BEARING 3  
SOUTH ABUTMENT (FIXED)

**BEARINGS WITH BEARING AREA LOSS**


AS-BUILT PER 1938 PLANS  
SOLE PLT: 9" x 1 1/2" x 11", WELDED TO BEAM  
MASONRY PLT: 12" x 2" x 1'-2"  
7/8" ANCHOR BOLTS, 2'-4" L  
4" HOOK

**LEGEND:**

- Spall
- Punky Concrete
- Indicates a change in condition from previous inspection
- Indicates a new condition not previously noted



PLAN  
BEARING 4  
SOUTH ABUTMENT (FIXED)



PLAN  
BEARING 5  
SOUTH ABUTMENT (FIXED)

**Sketch 3: Bearings 1 – 5, south abutment. From Routine & Special Member Report, dated 3/21/25.**

CITY/TOWN ASHFIELD	B.I.N. 0EF	BR. DEPT. NO. A-13-024	8.-STRUCTURE NO. A13024-0EF-MUN-NBI	INSPECTION DATE JUL 8, 2025
-----------------------	---------------	---------------------------	--	--------------------------------

**PHOTOS**

Photo 1: General topside, looking north.



Photo 2: General underside, looking south.

CITY/TOWN ASHFIELD	B.I.N. 0EF	BR. DEPT. NO. A-13-024	8.-STRUCTURE NO. A13024-0EF-MUN-NBI	INSPECTION DATE JUL 8, 2025
-----------------------	---------------	---------------------------	--	--------------------------------

**PHOTOS**

**Photo 3: South bridge seat, with deteriorated pedestals and bearings.**



**Photo 4: South abutment, beam 1 bearing.**

CITY/TOWN ASHFIELD	B.I.N. 0EF	BR. DEPT. NO. A-13-024	8.-STRUCTURE NO. A13024-0EF-MUN-NBI	INSPECTION DATE JUL 8, 2025
-----------------------	---------------	---------------------------	--	--------------------------------

**PHOTOS**

**Photo 5: South abutment, beam 2 bearing.**



**Photo 6: South abutment, beam 4 bearing.**

CITY/TOWN <b>ASHFIELD</b>	B.I.N. <b>0EF</b>	BR. DEPT. NO. <b>A-13-024</b>	8.-STRUCTURE NO. <b>A13024-0EF-MUN-NBI</b>	INSPECTION DATE <b>JUL 8, 2025</b>
------------------------------	----------------------	----------------------------------	---	---------------------------------------

**PHOTOS**

**Photo 7: South abutment, beam 6 bearing.**